

DATA Vehicles Refurbishment Pre-proposal conference

Questions from Bidders and corresponding answers from the City

1. Section 1.3 page 6 Interior. Side panels. Please clarify which side panels will be replaced.

Answer: See attachments 2 and 4

2. Please provide color number of the side panels.

Answer: See attachment 1 and 3

3. Please provide copy of parts disc for buses included in this project.

Answer: No parts disc are available. We have only hard copies.

4. Please provide bus serial numbers for buses included in this project.

Answer: See attachment 5 for serial numbers

5. Section 1.4 Refurbishment Schedule. Coach Crafters, Inc. requests 2 buses be made available for refurbishment.

Answer: 2 buses will be made available at one time for refurbishment.

6. In reference to the RFP on page 7 section 1.4 it states that all buses shall be moved by "flat-bed". It further states that the buses shall not be towed or driven. Midwest Bus Corporation is requesting that buses going to a facility within 10 miles be allowed to be driven to and from the refurbishment facility.

Answer: The City has no objection to driving the buses to a shop if within 10 miles from our facility and as long as the contractor has proof of license and insurance that would cover our vehicles in case of an accident.

Attachment -1

GILG

LOW FLOOR

SIDEWALL PANELS, INTERIOR LH


Item	Part No.	Description	Qty
1.	15-41712-000L	PANEL, SIDE INTERIOR REAR	1
2.	15-41733-000L	PANEL, INTERIOR, REAR	1
3.	15-41846-000	PANEL, SIDE INTERIOR INTERMEDIATE	6
4.	15-41907-000	PANEL, INTERIOR SIDEWALL, RR WHEELWELL	1
5.	15-50205-000L	PANEL, INTERIOR SIDEWALL, RR	1
6.	15-41914-009	PANEL, INTERIOR SIDEWALL	1
7.	15-48071-000	PANEL, INTERIOR SIDEWALL	1
8.	15-45645-000	PANEL, SIDE INTERIOR B-POST LH	1
9.	15-41898-000R	PANEL, SIDE INTERIOR B-POST LH	1
10.	15-51491-000	PANEL, SIDE INTERIOR, DRIVER'S	1
11.	15-41899-000L	PANEL, SIDE INTERIOR A-POST LH	1
12.	15-41925-000	PANEL, INTERIOR SIDEWALL FRT WHEELWELL	1
13.	15-41274L000	TRIM, CAP "J" MOLDING (CUT TO LENGTH)	A/R
14.	15-41001L000	MOLDING, TRIM "H" MOLDING (CUT TO LENGTH)	A/R

Attachment - 2

LOW FLOOR

GILLIE

SIDEWALL PANELS, INTERIOR LH



*SHOWN FROM INSIDE LOOKING OUT.

15-0052-73946
15-003843
15-0052-73946

Attachment - 3

GILF

LOW FLOOR

INTERIOR SIDEWALL PANELS: RH 40'


Item	Part No.	Description	Qty
1.	15-41900-000	PANEL,SIDE INTERIOR REAR DOOR POST	1
2.	15-41936-000	PANEL, INTERIOR SIDEWALL	1
3.	15-41896-000	PANEL,SIDE INTERIOR INTERMEDIATE	3
4.	15-45650-000	PANEL, INTERIOR SIDE WALL	1
5.	15-41914-010	PANEL,INTERIOR SIDEWALL	1
6.	15-41900-000	PANEL,SIDE INTERIOR DOOR POST	1
7.	15-41907-000	PANEL-INTERIOR SIDEWALL	1
8.	15-46735M001R	PANEL,INTERIOR RR	1
9.	15-51722-000R	PANEL,SIDE INTERIOR REAR	1
10.	15-41274L000	TRIM-CAP, "J" MOLDING	A/R
11.	15-41001L000	MOLDING-TRIM, "H" MOLDING	A/R

Attachment - 4

LOW FLOOR

GILLIG

INTERIOR SIDEWALL PANELS: RH 40'



*SHOWN FROM INSIDE LOOKING OUT.

15-0102-73946
15-001847
15-0102-73946

0302	2003 GILLIG LOW FLOOR	15GGD201931073947
0303	2003 GILLIG LOW FLOOR	15GGD201031073948
0304	2003 GILLIG LOW FLOOR	15GGD201231073949
0305	2003 GILLIG LOW FLOOR	15GGD201931073950
0306	2003 GILLIG LOW FLOOR	15GGD201031073951
0308	2003 GILLIG LOW FLOOR	15GGD201431073953
0309	2003 GILLIG LOW FLOOR	15GGD201631073954
0311	2003 GILLIG LOW FLOOR	15GGD201X31073956
0315	2003 GILLIG LOW FLOOR	15GGD201131073960
0316	2003 GILLIG LOW FLOOR	15GGD201331073961
0317	2003 GILLIG LOW FLOOR	15GGD201531073962
0319	2003 GILLIG LOW FLOOR	15GGD201931073964
0320	2003 GILLIG LOW FLOOR	15GGD201031073965
0322	2003 GILLIG LOW FLOOR	15GGD201431073967
0324	2003 GILLIG LOW FLOOR	15GGD201831073969
0325	2003 GILLIG LOW FLOOR	15GGD201431073970
0326	2003 GILLIG LOW FLOOR	15GGD201631073971
0327	2003 GILLIG LOW FLOOR	15GGD201831073972
0328	2003 GILLIG LOW FLOOR	15GGD201X31073973
0329	2003 GILLIG LOW FLOOR	15GGD201131073974
0330	2003 GILLIG LOW FLOOR	15GGD201331073975
0331	2003 GILLIG LOW FLOOR	15GGD201531073976